

**ENGINEERING PR REQUEST**

<b>Particular:</b>	<b>Pillow Block</b>
<b>Classification</b>	<b>Equipment/Parts</b>
<b>Category:</b>	<b>Spare parts</b>
<b>Specs</b>	<b>P208</b>
<b>Model</b>	<b>-</b>
<b>Department:</b>	<b>Engineering</b>
<b>Unit/Pcs</b>	<b>4</b>
<b>Requested by:</b>	
<b>Purpose of PR:</b>	<b>For replacement of defective pillow block of perforated pipe blower</b>

**Attached sample picture here if needed**

